

Short Block Service 4/6/09






# Crack Detection Magnafluxing Magnetic Fluorescent Inspection iron powder is applied within a liquid cracks appear as white streaks under black lights Dye Penetrant cleaner, dye and developer








Short Block Service 4/6/09

## Cylinder Repair Cylinder Deglazing crosshatch pattern holds oil and promotes ring seating during break-in Cylinder Honing honing is used to correct damage up to .010° Cylinder Boring performed by machine











Short Block Service 4/6/09

### Engine Repair **Connecting Rods**

- milled cap design cracked rod design
- oil squirt holes
- number rods before disassembly inspect for scratches and knicks

- twist tolerances are usually less than .001" crank journal end tolerances usually within .0003"
- rod noise light metallic knock that is most audible on acceleration/deceleration



### Engine Repair **Insert Bearings**

- · replaceable
  - soft surface material allows foreign particles to be embedded in the bearing surface
- bearing construction
  - · steel backing
  - copper/lead lining
  - · babbitt surface
- · solid aluminum



### Engine Repair **Bearing Lubrication**

- oil is fed from the low load side of bearing
- · a cross drilled crankshaft or bearing groove distributes oil
- hydrodynamic lubrication efficiency decreases rapidly with increased bearing clearances
  - a minimum lubrication film of 000040" is required to prevent




### Engine Repair **Bearing Clearance**

- doubling bearing clearance increases oil leakage at the bearing by a factor of five
- excessive clearance can cause
  - · low oil pressure
  - · oil consumption
  - knocking



## Engine Repair **Bearing Crush**

- · the bearing shell extends beyond the parting surfaces by approximately .001"
- prevents bearing from spinning
- · assure good heat dissipation



### Engine Repair **Bearing Failure**

- dirt
- · misassembly
- · misalignment
- insufficient **lubrication**
- overloading or stress
- corrosion



Short Block Service 4/6/09



